

Maryland Inventory of Historic Properties

Addendum

MIHP Number: CARR-750

Property Name: Hipped-Roof-House

Property Address: Littlestown Pike (MD 97)
Westminster, Maryland

The Hipped-Roof-House located on Littlestown Pike has been demolished according to the *Phase I Cultural Resources Survey Report* prepared for the Carroll County Regional Airport by Coastal Caroline Research.

Demolished

CARR - 750

HIPPED-ROOF HOUSE

early 20th century

Littlestown Pike
Westminster vicinity

private

The hipped-roof house is an example of early twentieth century domestic architecture. It basically follows the four-square style with its box-like shape, hipped roof, and symmetrical fenestration. It has a hipped-roof dormer and a two-stack chimney that straddles the peak of the roof. The main facade has a three-bay, one-story entrance porch with a hipped roof.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

Demolished

SURVEY NUMBER: CARR-750

NEGATIVE FILE NUMBER:

UTM REFERENCES:

Zone/Easting/Northing

U.S.G.S. QUAD. MAP: WESTMINSTER

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Abandoned

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent () Good ()

Fair (X) Poor ()

THEME:

STYLE: Early Twentieth Century

DATE BUILT: 11

COUNTY: CARROLL

TOWN: WESTMINSTER VIC.

LOCATION: Littlestown Pike (MD 97)

TAX MAP 39 Block 1 P-1

COMMON NAME: Hipped-Roof House

FUNCTIONAL TYPE: Residence

OWNER: Stenerson Realty Co.

ADDRESS:

ACCESSIBILITY TO PUBLIC:

Yes () No (X) Restricted ()

LEVEL OF SIGNIFICANCE:

Local () State () National ()

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone (X) Brick () Concrete () Concrete Block ()
2. Wall Structure
 - A. Wood: Log () Post and Beam () Balloon (X)
 - B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - C. Iron () D. Steel () E. Other
3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum () Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other:
4. Roof Structure
 - A. Truss: Wood (X) Iron () Steel () Concrete ()
 - B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:

Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds (X)
Ells () Wings () Other:Roof Style: Gable () Hip (X) Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:

Number of Stories: 2 1/2

Number of Bays: 3 X 2

Approximate Dimensions:

Entrance Location: center

THREAT TO STRUCTURE:

No Threat () Zoning () Roads ()

Development () Deterioration ()

Alteration () Other:

LOCAL ATTITUDES:

Positive () Negative ()

Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Hipped-roof dormer on front.
Double chimney at peak of roof.
Hipped-roof, two-bay entrance porch.

RELATED STRUCTURES: (Describe)

none

STATEMENT OF SIGNIFICANCE:

example of early 20th century rural architecture

REFERENCES:

1862 Martenet's Map:
1877 LG & S Atlas:

SURROUNDING ENVIRONMENT:

Open Lane (☒) Woodland (☐) Scattered Buildings (☐)
Moderately Built Up (☐) Densely-Built Up (☐)
Residential (☐) Commercial (☐)
Agricultural (☐) Industrial (☐)
Roadside Strip Development (☐)
Other:

RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:

7/11/83

U.S.G.S. MAP
WESTMINSTER, MD.
1:24000 SCALE





CARR- 750

HIPPED - ROOF HOUSE

Littlestown Pike

Westminster vicinity

not found

8/93

Photo By Joe Getty